

REPORTS WILL CHECK THIS IN JST
TO REPORT TO FOLLOW FOR ODEW.

2336

January 2, 1959

G.E. Simpson.

Release of
Flammable liquid

K-1401, South door of retubing area.

G.S. Hensley

8:00

Discovered by Guard Lt. Linkous at 7:40 P.M.

At 8:00 P.M. G.S. Hensley notified Fire Captain to check on a flammable liquid leaking from a drum located at South door of retubing area, K-1401 building.

Checked the condition and found a small quantity of Isopropanol liquid (99%) had leaked from a full 55 gallon drum, the leak was at the valve where it was screwed into drum. Maintenance supervisor notified that the drum should be placed ~~placed~~ in an upright position, maintenance performed this operation by using a drum handling rig.

A tag was placed on valve stating the defect.

Firemen used water from a 2½ gallon extinguisher to wash down the small area.

none

